Building Code Requirements and Specification for Masonry Structures
TMS 402-22, TMS 602-22 and Companion Commentaries

Errata
September 22, 2022

Page	Section, Article, Eq. or Fig. No.	Errata
C-157	Section 9.3.5.4	Change Section 9.3.4.1.2 to 9.3.3.1.2
C-161	Section 9.3.5.6.2.3	Change the equation at the top of the page from $c \geq \frac{l_w}{600\left(1.5C_d\delta_{ne}/h_w\right)}$ to $c \geq \frac{l_w}{600\left(\delta_{MCE}/h_w\right)}$
C-211	Table 13.2.2.3	For "Wood Light Framing, Corrugated Sheet metal", in the bottom line of "Other Requirements", correct 30 ft (9.14 mm) to 30 ft (9.1 m) and to be consistent with other entries later in the table.
C-244	Section C.3	Modify as follows: "The rotational deformation demand on plastic hinges shall be determined by imposing the ~~design~~ displacement, δ_{MCE} , at the roof level of the yield mechanism. The rotational deformation capacity of plastic hinges shall satisfy C.3.1 to C.3.3."

Watch https://masonrysociety.org/errata/ for possible additional errata.