

**Building Code Requirements and Specification for Masonry Structures
(TMS 402-08/ACI 530-08/ASCE 508,
TMS 602-08/ACI 530.1-08/ASCE 6-08
and Companion Commentaries)**

Errata

April 16, 2012

Watch www.masonrysociety.org/2008MSJC/Errata.htm for possible additional errata.

Page	Section or Article No.	Errata
C-19	1.13.3.2	Change Table 3.1.8.2.1 to Table 3.1.8.2
C-24	1.17.4.3.1	Modify as shown underline: 1.17.4.3.1 <i>Design of nonparticipating elements</i> — Nonparticipating masonry elements shall comply with the requirements of Section 1.17.3.1 and Chapter 2, 3,4, <u>5</u> , or Appendix A. Nonparticipating masonry elements, except those constructed...
C-27	Table 1.18.3	Change line 2a to read “Proportions of site-mixed mortar, grout and prestressing grout for bonded tendons”
C-29	Section 2.1.2.3	at the end of the sentence add, “, except where specifically prohibited by Section 2.1.4.1.”
C-29	Section 2.1.4.1	Add a new sentence at the end of this Section as follows: “The stress increase permitted by Section 2.1.2.3 shall not be applied to allowable anchor bolt loads.”
C-37	Text box between 3.1.3 and 3.1.4	Change 1.17.4.3 to 1.17.3.2.6.1.1. & 1.17.4.3.2.4
C-40	Eq. 3-14	Delete extra f'_m in the denominator (there should only be one).
C-48	4.4.3.7.2	Correct section reference from 4.4.3.7.2 to 4.4.3.7.4
C-68	A.3.4.1.2	Change V_s in Eq. A-9 to V_{ns}
C-68	A.3.4.1.2.1	Change λ_w in two places in Eq. A-12a and also in Eq. A-12b to l_w
C-79	3.3.6.6	Change 3.3.6.6 to 3.3.6.5.1 in 3 locations
C-79	3.3.6.6(a)	Change 3.3.6.8(a) to 3.3.6.5.3(a)
C-81	A-12a and b	Change λ_w in two places in Eq. A-12a and also in Eq. A-12b to l_w
C-82	A.3.6.8(a)	Change A.3.6.8(a) to A.3.6.6.2(a)
C-78	Eq. 3-24	Change 0.05 to 0.20
S-14	Table 5	Change line 2a to read “Proportions of site-mixed mortar, grout and prestressing grout for bonded tendons”

S-26	3.4 E.6	Change 3.4 D.4 and 3.4 D. 5 to 3.4 E.4 and 3.4 E.5
S-31	3.3 F.2	Change 3.3 F.2 to 3.3 D.2 – 4
S-31	3.3 F.6	Change 3.3 F.6 to 3.3 D.5
S-31	3.3 F.7	Change 3.3 F.7 to 3.3 D.6
S-32	3.3 E.2	Change 3.3 E.2 to 3.3 D.2-4
CC-8	1.2.2	Change Figure 1.2.2-1 to Figure CC-1.2.2-1
CC-15	Fig. 1.9-3	Change Fig. 1.9-3 to Figure CC-1.9-3
CC-29	Table CC-1.17.3.2	Add a footnote 1 after the table title and then below the table add footnote 1 as follows: ¹ Section and Chapter references in this table refer to Code Sections and Chapters.
CC-45	2.1.9.7.1.2	Change 2.1.9.7.1.2 to 2.1.9.7.1.1
CC-55	Commentary Section 3.1.6.2	Change ASTM E448 to ASTM E488.
CC-55	3.1.6.2	In the last sentence change <i>N</i> to ϕ
CC-57	Commentary Section 3.1.6.3.1.2	In the last sentence, change “3.2 B” to 3.2 A”
CC-59	3.3.3.1	Change reference 3.2 to 3.10
CC-62	3.3.4.1.2.1	Change reference 3.2 to 3.10
CC-62	3.3.4.1.2.3	Change reference 3.2 to 3.10
CC-61	3.3.3.5	In the last paragraph just prior to Section 3.3.3.6 change “...Reference 3.2, Report Nos. 3.1(a)-2, 3.1(c)-1, 3.1(c)-1, ...” to “...Reference 3.10, Report Nos. 3.1(a)-2, 3.1(c)-1, 3.1(c)-2...”.
CC-83	6.1.1	In the first paragraph, change Figures 6.1-1 and 6.1-2 to Figures CC-6.1-1 and CC-6.1-2
CC-89	Commentary Figure CC-7.2-1	Change the units of the “y” axis to psf (kPa).
CC-95	A.3.4.1.2	Change V_s to V_{ns} in two places
SC-18	References	Correct the reference numbers to be consecutive so that second 2.14 becomes 2.15, 2.15 becomes 2.16, and 2.16 becomes 2.17
SC-22	3.5 C	Change Table SC-7 to Table 7 in three places.

Watch www.masonrysociety.org/2008MSJC/Errata.htm for possible additional errata.